WHAT TO EXPECT DURING AN INSPECTION



MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY Underground Storage Tank Branch

UST INSPECTIONS

Conduct approx 1,000 inspections/yr

55% of inspections result in enforcement actions

Assess approx \$250,000 in civil penalties each year

EXPECTATION 1


Letter notifying you of the inspection which includes:

- Date
- Time
- Inspector
- Phone number to contact if re-scheduling is required
- List of all records that need to be present during inspection


EXPECTATION 2 on site with the city of the




EXPECTATION 3 - DISPENSERS TO BE OPENED




SHEAR VALVES ANCHORED, SHUT, AND MOUNTING BRACKET OK?




SHEAR VALVE NOT ANCHORED



FLEX CONNECTORS OK?




PIPING ELONGATION





Fuel in spill bucket



SPILL BUCKET INTEGRITY



Check for splits or tears



EXPECTATION 5 - CHECK OVERFILL PREVENTION

Determine depth it is set



						4			6	
MISS	SISSIPP	I DEPA	RTMEN	IT OF	ENVIRO	NMEN	TAL C	UALITY		
	ANNUA	L OVER	FILL PR	EVENT	ON DEVI	CE INS	PECTI	ON		
This form may 1	ap utilized to d	bowment his	pection of \$4	ST gyarfill on	evention daylo	M6.		Date of	(Inspection	
hispaction of all	of a recogniz	ed Industry 1	no enubecons	ក្រាត្តកូបខែជាមក	ara recommen	ndaa precil	ca the 'Mi	080	i	
Overfili Davice	repection '	ceante, ont	lmed bolow	mov he HID 71	ed ne				100	
bally same		Person Conducting Inspection								
consulte Kiosk 12694					Reporter's Number KLEVIA EILIS					
Physica Address Abo S Church St.					COMPONY Ellis Enterprises, LLC					
Louis	State MS	ÇIIS	Philad			7. E	<u> </u>			
Winston					poder a Signetur	-		Coats Co	14-09	
	TOTAL TOTAL	Section 199	A-Pil Prov	ention De	vice inepe	ction	Market Co.		917498	
Type of Overful Co	7.4	Ball Float			Orcp Tube			🗆 Electronia	. Alerm	
		ADEO O	Til Preve	ntian Davi	ce inspecti	on Proce	dure			
1. Somet fitting/ope and visually confirm that be \$ 505) valve is present and in good condition.										
Ball Float 2. Ensure that but four value is at proper height within the tank (restricts flow at 90% tank capecity) Valve 3. Ensure at tank top fittings one in good condition and appear to to vapor tight.									17.1	
AGIAC	4 If there	is arw outsil	ion about tun	ations ity, re-	move, inspect	, and reinei	all cavics	oled ston sea)	₩ <u>`</u> .	
····	1 Bernaulo hair 61 can and idevetty confirm that drop tube shutelf device is present and and obstructed.									
Drop Tube Shuteff	2. Ensure that the drop fulse shutoff is at proper height within the task (abute-off flow of 95% task capacity). 3. Ensure that tight-fill adaptor on fill riser is in good condition.									
	4. If there is any quastion ebeth functionality, remove, inspect, and retrainif (see note below)									
······································	1. Romby	 Remove the electronic glass device from the tank and visually mapted to demage or corrusion. 								
Electronic	2. Ensure	 Ensure the device functions correctly by causing an alarm condition (a.g. submerge in field). 								
Alarm	Remarkell the electronic starm device in the tank (see note below) at the proper rangit which are the tank. Ensure that alarm is audiate and identifiable by the delivery person as an overfall starm.									
N	ote: MDEQ d	erification	as a UST ir	ıstallar is re	ani ot benlup:	tall over⊓l	preventi	on devices	cm=:15007	
		具好納	nspection	n Result	for the Y	ear	2009		100	
Tenk 10 (product slored) Reg			18 Prom	Huy	OFFRU				<u> </u>	
Device present (yau'no) 125			485	1105	Ves		<u> </u>			
In good condition (yearns)			3,00	2005	294		<u> </u>			
Set at extract height (yes/he)		170	100	no		<u> </u>	. 	<u> </u>		
Tark (op Blings Buhl (yoshio) Ve S			yes.	183	125		<u> </u>	<u> </u>	-} . -	
Alerm sudible	(yeshto)	. ') 	<u> </u>			<u> </u>		 	
inspection result (PeauFeil) Fig.)			Fost	Fail	FAIL		<u> </u>		<u> </u>	
Commerte:	A11. 2	MnK5	HAVE	6"	£ 2000	106	<u> يو و</u>	need		
										
						2713120-0				
PRODUCE	BY THE MIS	SISSIPPI DEF	T, OF ENVIR	ONMENTAL C	DUALITY, OPEN	CE OF POL	LUTION CO	NTROL, UST B	RANCH	

BALL FLOAT DEVICE NOT SET @ CORRECT HEIGHT

VERIFY EXISTING OVERFILL DEVICE



EXPECTATION 6 - OPEN ALL MANWAYS



MANWAYS SHOULD BE CLEAR OF WATER AND SOIL



PROBLEMS IN SUMPS?



NO CATHODIC PROTECTION



CHECKING VOUR ECTION EXPECTATION SYSTEM

RECTIFIER ON, WORKING AND ACCESS TO PIPING







RECTIFIER NOT OPERATING PROPERLY





EXPECTATION 8 CORDS

RECORDS SHOULD INCLUDE:

- 12 months leak detection records for piping
- 12 months leak detection records for tanks
- Annual testing records (usually include:)
 - Shear valve check
 - Automatic line leak detector test
 - Spill bucket test
 - Overfill device inspection
- Cathodic protection 3 year test for tanks, pipes, and terminations
- 60 Day rectifier log (if applicable)
- Recent repair records

COMMON PAPERWORK ISSUES

Missing and misplaced records
Records are not easily accessible
Issues documenting <u>a fail</u> are not fixed

Registration of tanks / piping with MDEQ commonly is not what is actually out there.



Leak detection records indicating a leak are not reported to MDEQ

EXPECTATION 9 – FOLLOW-UP LETTER FROM MDEQ



STATE OF MISSISSIPPI

PHIL BRYANT GOVERNOR

MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY

GARY C. REGARD, EXECUTIVE DIRECTOR

July 19, 2016

To Whom It May Concern:

IRE: Underground Storage Tanks (USTs)

3405 Cayce Road Byhalia, Mississippi Unregistered Location

The Mississippi Department of Environmental Quality (MDEQ) has determined that if an underground storage tank (UST) was empty or filled with water prior to 1988 (pre-88 tank), the tank has been permanently closed in accordance with the requirements of that time. Our office does not require sampling to occur or the tank to be removed from the ground or filled with an inert material (.e. concrete, drilling mud).

There are no USTs registered with MDEQ at 3405 Cayce Road in Byhalia. If the USTs were out of use prior to adoption of the UST Regulations (December 22, 1988), the USTs were not typically registered with our department.

Please Note: If contamination is discovered resulting from the UST, the current tank owner/property owner at the time of discovery is responsible for any remedial action. Due to this item, our office recommends an assessment (soil or groundwater sampling) to be performed prior to the purchase of properties containing pre-88 tanks. But again, it is not required by our office.

If a UST has been out of service prior to 1,988 and the owner decides to permanently close the tank (i.e. remove from the ground or close in place with fill material), the owner is not required to use a Mississippi Certified Contractor to permanently close the UST. However, due to safety reasons our office suggests the use of a Mississippi Certified Contractor for the permanent closure activities.

We appreciate your apparent concern for human health and the environment. Should you have any questions or comments, please do not hesitate to contact me at (601) 961-5117.

Sincerely,

Lynn Chambe UST Branch Either,

Inspection found no violations

No Further Action (NFA) Letter

Or,

Inspection found violations

Notice of Violation (NOV)

Letter

COMPLIANCE CYCLE

Inspection



1st Notice of Violation (60 – 90 Days to correct)

- Attend administrative conference to discuss penalty /correcting violations, or
- Attend UST Workshop in lieu of paying penalty and correct violations

2nd Notice of Violation (30 days to correct)

3rd Notice of Violation (14 days to correct)

Delivery Prohibition enforced for any unresolved violations



EXPECTATION 10 - NO FURTHER LEXPECTATION 10 -

level. Therefore, this site does not pos No further action is necessary to meet p

We greatly appreciate your cooperation any questions or comments, please call

Sincerely,

